

General Environmental Incident Summary

Incident: 1994 **Date/Time Notice:** 7/19/2013 1335 **DEM Incident No:**
Responsible Party: Basin Electric Power Cooperative

Date Incident: 7/18/2013 **Time Incident:** **Duration:** 2 hours

County: Mercer **Twp:** 145 **Rng:** 88 **Sec:** 24 **Qtr:**

Lat: 47.36419 **Long:** -101.83330 **Method:** Derived from TRS

Location Description: Antelope Valley Station
294 County Road 15
Beulah, ND

Submitted By: Erin Fox Dukart **Affiliation:**

Address:

City: **State:** **Zip:**

Received By:

Contact Person: Jeff Hansen
1717 East Interstate Avenue
Bismarck, ND 58503

Distance Nearest Occupied Building:

Type of Incident: Vehicle Accident

Description of Released Contaminant: Fuel oil

Volume Spilled: 80.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

A contractor was changing a tire on a scraper when the arm of the tire machine hit the quick fuel nozzle fitting on the scraper fueling line, resulting in a fuel leak from the fitting.

Risk Evaluation:

None.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

A loader was used to create a berm around the fuel spill. The loader was then used to remove the contaminated soil. The soil was hauled to the ash pit where it was spread out thin to allow the fuel to evaporate and will be covered with fly ash on Monday. All contaminated soil was dug out and enough soil was removed to get down to clean soil.

Wastes Disposal Location: Oil contaminated soil was disposed of in the ash pit.

Agencies Involved:

Updates

Date: 7/19/2013 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Appropriate final disposal of contaminated soil in question. Referred to Tillotson, WM for review and any potential follow-up.